

Report ID: 18,197,443 Version: 1 10 Jul 2018 Created:

Make:	Volvo	Model:	XC60	Body Style:	SUV		Pass	Fail	N/A
Year:	2,012	Registration:	GFL467	Reg Expiry:	01 Nov 2018	Engine	I	<u> </u>	I
WoF Expiry:		Odometer:	100,874 Kms	Good No:	18197443	Oil level	~		
VIN:	YV1DZ8256C2276116	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Dauta hava a at	harria d'anna ad a d	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	nical inspection prior to	purchase and the	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	sc	-0	S P SC S P	-161-	sc	Radiator / Hoses (visual)	~		
S = scratch	RE	A U			The second	Transmission	-		
D = dent	s sc			TIN	SDC	Operation	~		
R = rust PT = paint def				$\prod$		Noise	~		
C = crack						Clutch	-		~
P = pin dent	-110				거네	CV joints	~		
* = decals	ssc 919			- Jul	<b>AID</b>	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs	$\neg \varnothing$	( )		SC	Performance	~		
Dealertee	<u></u>	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body Inst	pection Comments			, ,	, ,	Tyres (lowest observed tread	-	of tyre	l es)
								mm	
						Right front		7	mm
						Left rear			mm
Conditions During Body Inspection:						Right rear		, 7	mm
Conditions During Body Inspection: Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	A					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ard Average					Window winder FL	~		
	I					Window winder FR	~		
General (	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	L	1
Road Conditions During Test Drive: Wet						Central locking	~		
			Wet			Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		-
L						<u> </u>	۱ <sup>-</sup>		
Inspected by: Donovan Matara Date: 10 Jul 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....