

Report ID: 18,197,721 Version: 1 26 Jun 2018 Created:

Make:	Honda	Model:	FIT	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,008	<b>Registration:</b>	JJC995	Reg Expiry:	24 Sep 2018	Engine	1		I
WoF Expiry:	30 Nov 2018	Odometer:	110,382 Kms	Good No:	18197721	Oil level	~		
VIN:	7AT08G2YX15069455	Next Service:	113179	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	<u>s</u>			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	sc d			215	HIV	Operation	~		
PT = paint defe				$\left[ \left( \right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HB				74116	CV joints	~		
* = decals	R PT SC 91			The second		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front 5 mn			mm
						Right front			mm
						Left rear	-		mm
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
						Spare No			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
<u></u>	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	· ·					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
			-			Remote locking	~		
-	ning Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Stuart Melbourne Date: 26 Jun 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....