

Report ID: 18,199,558 Version: 3 Created: 05 Oct 2018

Make:	Honda	Model:	Inspire	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2004	Registration:	GNL442	Reg Expiry:	27 Nov 2018	Engine	1	I		
WoF Expiry:	20 Jul 2019	Odometer:	167,278 Kms	Good No:	18199558	Oil level	~			
VIN:	7AT08G0TX12100374	Next Service:	Due	Service Histor	V: No	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	or an additional c	harge.	Coolant condition	~			
						Performance	~		+	
Key:		-0	ls	-01-	s	Radiator / Hoses (visual)	~		+	
S = scratch						Transmission	Transmission			
D = dent R = rust	sc di			TIS	HILLS	Operation	~			
R = rust PT = paint defe				\prod		Noise	~			
C = crack				+		Clutch	-		~	
P = pin dent					세비	CV joints	~			
* = decals	sc 916			The	EIPErs	Wheel bearings	~		+	
SC = stone chips						Brakes				
W = significant scuffs S S S						Performance				
Note: come defecte & blamiches may not be displayed in the diagram						Hand Brake	~		+	
Body Inspection Comments										
						Tyres (lowest observed tread depth of tyres)			mm	
						Right front		.0	-	
						Left rear		.0	mm	
								.0	mm	
Conditions During Body Inspection: Dry						Right rear	3.0 mm		mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
Minor Oil leak						Suspension				
	an					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation	~			
Good						Electrical / Accessories	1			
Seats	0000					Head lights	~			
Carpets	Good					Tail lights	~			
	Cood					Indicators	~			
Panels	Good					Dashboard warning lights		~		
Dashboa	rd Average					Wipers (front & rear)		~		
Dastibua						Window winder FL	~			
	· .					Window winder FR	~			
General Comments Has CMS light on dash.						Window winder RL	~			
Has CMS lig	ht on dash.					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1		•	
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking			~	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~	
						L	1	1		
Inspected by: Dion Mair Date: 02 Oct 2018										
I have read and understood this condition guide. Name:										