

Basic Vehicle Condition Guide

Report ID: 18,199,821


Version:

Created: 28 Jun 2018

Make: Model: Hyundai 130 **Body Style:** Wagon Year: 2,010 Registration: FSN337 Reg Expiry: 20 Jul 2018 **WoF Expiry: Odometer: Good No:** 06 Nov 2018 18199821 154,516 Kms VIN: KMHDB81DMBU10862 **Next Service: Service History:** 160000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips on front windscreen

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

28 Jun 2018 Inspected by: Xinghui Lin Date:

Name:

| | Pass | Fail | N/A | |
|------------------------------|--|---------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\times \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | |
| Left front | | 5 | mm | |
| Right front | | 5 | mm | |
| Left rear | 5 | | mm | |
| Right rear | 5 | | mm | |
| Spare | Yes | | | |
| Suspension | 1 | | | |
| Suspension performance | ~ | | | |
| Steering performance | V V | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | 1 | 1 | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | \(\times \) \(\t | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 1 | | | |
| Central locking | · | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | <u> </u> | | V | |
| Reversing camera | | | V | |
| g camera | | | | |

Signature: