

Basic Vehicle Condition Guide

Report ID: 18,200,139


Version: 2

Created: 17 Jul 2018

Make: Model: Ford **Body Style:** Utility Ranger Year: 2,014 Registration: Reg Expiry: HRS568 29 Sep 2018 **WoF Expiry: Odometer:** 16 Jul 2019 **Good No:** 18200139 185,347 Kms VIN: MNAUMFF50EW29760 **Next Service: Service History:** 194000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Left tail light cracked

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Good		
Panels	Good		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Dion Mair Date: 29 Jun 2018

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System	•	•	•
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	3	.0	mm
Right front	3.0		mm
Left rear	3.0		mm
Right rear	3.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		!	
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	V V V V V V V V		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~

Signature: