

## **Basic Vehicle Condition Guide**

Report ID: 18,200,305


Version:

Created: 27 Sep 2018

Make: Model: Mazda CX-7 **Body Style:** SUV Year: 2007 Registration: LLL912 Reg Expiry: 12 Jul 2018 **WoF Expiry: Odometer: Good No:** 18200305 18 Apr 2019 127,808 Kms VIN: 7AT0C13PX14102592 **Next Service: Service History:** No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Rear windscreen water sprayer fail

**Conditions During Body Inspection:** Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments	5
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

## **General Comments**

Transmission and engine noisy, needs attention Suspension knocking

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: **Timing Chain** 

**Evidence of Cam Belt Replacement:** Kms: Not Applicable

Inspected by: Ca Thach 19 Jul 2018 Date:

Name: .....

4 4	.5	mm
4 4	.5	mm
4	.5	mm
6	.5	
		me := -
6	.5	mm
	6.5 m	
Yes		
	~	
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		L
1		
		V
		<i>v</i>
	V V V V V V	V V V V V V V V V V V V V V V V V V V

Signature: .....