

Basic Vehicle Condition Guide

Report ID: 18,200,572


Version: 1

Created: 29 Jun 2018

Make: Model: Hyundai lx35 **Body Style:** SUV Year: 2,014 Registration: HTG519 Reg Expiry: 29 Dec 2018 **WoF Expiry: Odometer:** 25 Dec 2018 **Good No:** 18200572 123,779 Kms VIN: KMHJU81GSFU038877 **Next Service: Service History:** 125000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Dirty

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Stuart Melbourne

Created	a: 2	9 Jun 2	018	
	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	VVV			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	\(\times \)			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	>			
Clutch			~	
CV joints	>			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	l depth	of tyre	es)	
Left front	-	7	mm	
Right front		7	mm	
Left rear		3	mm	
Right rear	(5	mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	V V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	> > >			
Wipers (front & rear)	V			
Window winder FL	~			
Window winder FR	VVV			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera	~			

29 Jun 2018

Date: