

Basic Vehicle Condition Guide

Report ID: 18,200,810


Version:

Created: 20 Aug 2018

Make: Model: Hiace **Body Style:** Minibus Toyota Year: 2,013 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 26 Jun 2019 18200810 112,474 Kms VIN: 7AT0H60FX18112637 **Next Service:** 122000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** No

Date: 28 Jun 2018 Inspected by: **Bobby Zhong**

Kms:

	Pass	Fail	N/A
Engine		•	
Oil level	~		
Smoke & fumes	v		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	4	.0	mm
Right front	4.0		mm
Left rear	4.0		mm
Right rear	4.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	V V V V V		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	3		
Central locking	~		
Remote locking	1		
Sat. Nav. (basic test only) Reversing camera			~

I have read and understood this condition guide.

Name:

Signature: