

Basic Vehicle Condition Guide

Report ID: 18,201,093


Version:

Created: 01 Jul 2018

Make: Model: Holden Colorado **Body Style:** Utility Year: 2,013 Registration: Reg Expiry: 19 Mar 2019 GZG969 WoF Expiry: **Odometer:** 03 Apr 2019 **Good No:** 18201093 140,885 Kms VIN: MMU148EH0DH63642 **Next Service:** 142000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Very dirty

Interior Comments			
Seats	Poor		
Carpets	Poor		
Panels	Poor		
Dashboard	Poor		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

01 Jul 2018 Inspected by: Stuart Melbourne Date:

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	V V			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	\(\triangle \)			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	v			
Clutch	~			
CV joints			~	
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front		6	mm	
Right front	1	1	mm	
Left rear		4	mm	
Right rear	1	1	mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	<i>v</i>			
Shock absorbers	~			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	V V V			
Window winder FL	\(\times \)			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	'			
CD (basic test only)	~			
Number of keys	2		1	
Central locking	V			
Remote locking	'		<u> </u>	
Sat. Nav. (basic test only)			'	
Reversing camera				

Signature: