

Basic Vehicle Condition Guide

Report ID: 18,201,462

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Created: 02 Jul 2018

Pass

1


Fail

N/A

Make: Model: Holden Colorado **Body Style:** Utility Year: 2,016 Registration: JRM906 Reg Expiry: 30 Jul 2018 WoF Expiry: **Odometer:** 31 Mar 2019 **Good No:** 18201462 33,656 Kms VIN: MMU148EK0GH63892 **Next Service: Service History:** 46500 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

John Lindsay

No

Kms:

Name:

Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front		7	mm
Right front	5		mm
Left rear		7	mm
Right rear		7	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	<i>V</i>		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	> > > > > > > > > > > > > > > > > > >		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~

02 Jul 2018

Signature:

Date:

I have read and	understood this	condition guide.