

Basic Vehicle Condition Guide

Report ID: 18,201,778

Version:

Created: 17 Jul 2018

Fail


N/A

Pass

Make: Model: Volkswagen T5 **Body Style:** Van Year: Registration: FHD227 Reg Expiry: 15 Sep 2018 2,010 WoF Expiry: **Odometer: Good No:** 18 Feb 2019 18201778 190,256 Kms VIN: WV1ZZZ7HZAH22264 Next Service: **Service History:** 223073

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Scratch left front door mirror.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

FWD. Slight engine fluid leak.

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System	•		
Coolant condition	~		
Performance	v		
Radiator / Hoses (visual)	~		
Transmission	,		
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		1	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		5	mm
Right front	5		mm
Left rear	7.5		mm
Right rear	7.5		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V V		
Shock absorbers	~		
Air Conditioning / Heater		1	
Operation	~		
Electrical / Accessories	,		
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\triangle \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	1	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			·

I have read and understood this condition guide.

Eddie Marsters

Name:

Signature:

17 Jul 2018

1

Reversing camera