

Basic Vehicle Condition Guide

Report ID: 18,201,853

Version:


Created: 02 Jul 2018

Make: Model: CT200H **Body Style:** Hatchback Lexus

Year: 2,011 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 27 Jun 2019 18201853 84,604 Kms VIN: 7AT0B010X18024750 **Next Service: Service History:** 94,600kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

No spare wheel, repair kit only.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Tidy.

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Sharp looking, tidy hybrid Lexus.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

02 Jul 2018 Inspected by: **Daryll Timms** Date:

Γ			1
Engine	Pass	Fail	N/A
Oil level	V		
Smoke & fumes			
Performance	V		
Noise	1		
Cooling System			
Coolant condition			
Performance			
Radiator / Hoses (visual)	<i>V</i>		
Transmission			
Operation	•		
Noise	<i>'</i>		
Clutch			-
CV joints	-		
Wheel bearings	~		
Brakes			1
Performance	~		
Hand Brake	'		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	(5	mm
Right front	(5	mm
Left rear	6		mm
Right rear	į	5	mm
Spare		No	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	\(\rac{2}{}		
Remote locking	~		
Sat. Nav. (basic test only)	+		1
Reversing camera	~		–
versing camera			

I have read and understood this condition guide.

Name:

Signature: