

Report ID: 18,202,054 Version: 1 Created: 06 Jul 2018

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2,017	Registration:	KZN932	Reg Expiry:	08 Nov 2018	Engine	1	1	1
WoF Expiry:	07 Nov 2020	Odometer:	11,901 Kms	Good No:	18202054	Oil level	~		
VIN:	MR0KA3CD501203662	Next Service:	15,000 kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	r		
	port is not a warranty	aration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0		-161-	S W	Radiator / Hoses (visual)	v		
S = scratch						Transmission			
D = dent	w 6/6			The		Operation	~		
R = rust PT = paint def				í l n	JHIH	Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		
* = decals	sc 916			AL	EIIP I	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs SW SPW SW						Performance	~		
		Note: son		may not be disn	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	ofture	
						Tyres (lowest observed tread depth of tyres) Left front 6.1 mn			
							6		mm
						Right front	6		mm
						Left rear		.4	mm
Conditions During Body Inspection: Wet						Right rear	5.9 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	mermspectic	<u>on comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories	1		
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Anna-Lise Ferguson Date: 06 Jul 2018									
I have read and understood this condition guide. Name:									