

Basic Vehicle Condition Guide

Report ID: 18,202,238


Version: 3

Created: 08 Nov 2018

Make: Model: Mazda Premacy **Body Style:** SUV Year: 2006 Registration: KSQ14 Reg Expiry: 20 Aug 2018 WoF Expiry: **Odometer: Good No:** 11 Jul 2019 92,250 Kms 18202238 VIN: 7AT0C133X17123995 **Next Service:** Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



All tyers low

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Dion Mair Date: 03 Jul 2018

Name:

	Pass	Fail	N/A	
Engine				
Oil level	×			
Smoke & fumes	×			
Performance	×			
Noise	×			
Cooling System		-	1	
Coolant condition	×			
Performance	×			
Radiator / Hoses (visual)	×			
Transmission				
Operation	×			
Noise	×			
Clutch			x	
CV joints	×			
Wheel bearings	×			
Brakes				
Performance	×			
Hand Brake	×			
Tyres (lowest observed tread depth of tyres)				
Left front		6	mm	
Right front	(6	mm	
Left rear		2	mm	
Right rear		2	mm	
Spare		Yes		
Suspension				
Suspension performance	×			
Steering performance	×			
Shock absorbers	×			
Air Conditioning / Heater				
Operation	×			
Electrical / Accessories				
Head lights	×			
Tail lights	×			
Indicators	×			
Dashboard warning lights	×			
Wipers (front & rear)	×			
Window winder FL	×			
Window winder FR	×			
Window winder RL	×			
Window winder RR	×			
Rear view mirrors	×			
Radio (basic test only)	×			
CD (basic test only)	×			
Number of keys	2			
Central locking	×			
Remote locking	×			
Sat. Nav. (basic test only)			X	
Reversing camera			×	

Signature: