

## **Basic Vehicle Condition Guide**

Report ID: 18,252,642


Version: 1

Created: 08 Aug 2018

Make: Model: Hiace **Body Style:** Minibus Toyota Year: 2,013 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 28 Jun 2019 18252642 84,534 Kms VIN: **Next Service:** 7AT0H60FX18111773 94000 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

**General Comments** 

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: No.

No

Kms:

Inspected by:	Bobby Zhong	Date:	29 Jun 2018
---------------	-------------	-------	-------------

Name: .....

Pass  V  V	Fail	N/A
<i>V</i>		
ν ν		
<b>'</b>		
~		
~		
~		
~		
~		
~		
~		
		~
		~
~		
~		
~		
depth	of tyre	es)
7.	.0	mm
		mm
		mm
		mm
	Yes	
~		
~		
~		
		.1
~		
~		
~		
~		
~		
~		
~		
~		
		~
		~
~		
~		
		~
2		1
~		
		·
		.,
	I	V
	/	/

Signature: .....