

Report ID: 18,252,996 Version: 1 Created: 01 Jul 2018

Make:	Mazda	Model:	CX-9	Body Style:	SUV		Pass	Fail	N/A
Year:	2,012	<b>Registration:</b>	GGL790	Reg Expiry:	06 Jan 2019	Engine	1		L
WoF Expiry:		Odometer:	112,305 Kms	Good No:	18252996	Oil level	~		
VIN:	JM0TB10A4C0307936	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	SP			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			1
D = dent R = rust	s sc			215	HIVS	Operation	~		
PT = paint defe	ect NP	F I		$\left[ \left( \right) \right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIP				74116	CV joints	~		
* = decals SC 99 S						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w – signincan	W					Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
					Left front	front 3			
						Right front	3	3 mm	
						Left rear	5	5	mm
Conditions During Body Inspection: Wet Right r						Right rear	5	5	mm
						Spare	pare Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Steering performance							~		
Shoc							~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	<		
Carranta	Average					Tail lights	<		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dachhar	Average					Wipers (front & rear)	<		
Dashboa						Window winder FL	~		
	<b>-</b> .					Window winder FR	۲		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet							~		
Remote locking							~		
Engine Timing Mechanism:     Timing Chain       Evidence of Cam Belt Replacement:     Not Applicable     Kms:       Beversing camera									~
	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Xinghui Lin Date: 01 Jul 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....