

Report ID: 18,253,009 Version: 2 01 Jul 2018 Created:

Make: Mazda	а	Model:	Mazda6	Body Style:	Wagon		Pass	Fail	N/A
Year: 2,011		Registration:	FWA592	Reg Expiry:	13 Aug 2018	Engine	I	<u> </u>	L
WoF Expiry: 21 Jun	n 2019	Odometer:	75,137 Kms	Good No:	18253009	Oil level	~		
l	H105200212761	Next Service:	-,	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is		untina in mode	for any and miles as	Dauta hava nat	heen dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechanical ins	spection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	Ĺ	-0	S SD		S D	Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent				The	SDPTC	Operation	~		
R = rust PT = paint defect				$\int$	THA	Noise	~		
C = crack	1			+	SC SC	Clutch			~
P = pin dent						CV joints	~		
* = decals SSC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W S S P W S						Performance	~		
		Noto: com				Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftyre	) )
Stone chips on front windscreen									 mm
						Right front		1	-
						Left rear		1	mm
						Right rear		1	mm
Conditions During Body Inspection: Wet							4		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
		<u>incernspectio</u>	<u>eonnents</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Average						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	, weitige					Dashboard warning lights	~		
Dashboard	Average					Wipers (front & rear)	~		
						Window winder FL	~		
General Comm	onte					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Engino Timina	Machanisme	<b>T</b> ''	Chen in			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence of Cal	п вел керіас	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Xinghui Lin Date: 01 Jul 2018									
							-		

I have read and understood this condition guide.

Name: .....

Signature: .....