

## **Basic Vehicle Condition Guide**

Report ID: 18,253,153


Version:

Created: 06 Jul 2018

Make: Model: Holden Colorado **Body Style:** Utility Year: 2,012 Registration: Reg Expiry: GQS483 20 Jun 2018 WoF Expiry: **Odometer:** 26 Jan 2019 **Good No:** 18253153 148,928 Kms VIN: MMU145DH0DH6490-**Next Service: Service History:** 159,000kms No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Stone chipped screen.

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Ok.

Interior Comments					
	Seats	Average			
	Carpets	Average			
	Panels	gear knob rubber worn.			
	Dashboard	scuffs & screw hole.			

	_
General	Comments

Good 4x4 flat deck ute.

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** No

Date: 06 Jul 2018 Inspected by: **Daryll Timms** 

Kms:

	Pass	Fail	N/A			
Engine						
Oil level	~					
Smoke & fumes	V V					
Performance	~					
Noise	~					
Cooling System						
Coolant condition	~					
Performance	~					
Radiator / Hoses (visual)	~					
Transmission						
Operation	~					
Noise	~					
Clutch	~					
CV joints	v v					
Wheel bearings	~					
Brakes						
Performance	~					
Hand Brake	~					
Tyres (lowest observed tread	depth	of tyre	es)			
Left front	(	5	mm			
Right front	(	5	mm			
Left rear	- 2	2	mm			
Right rear	- 2	2	mm			
Spare Yes						
Suspension						
Suspension performance	~					
Steering performance	~					
Shock absorbers 🗸						
Air Conditioning / Heater						
Operation 🗸						
Electrical / Accessories						
Head lights	<i>V</i>					
Tail lights	•					
Indicators	•					
Dashboard warning lights	•					
Wipers (front & rear)  Window winder FL	V V V					
Window winder FR	~					
Window winder RL Window winder RR			<i>V</i>			
Rear view mirrors						
Radio (basic test only)  CD (basic test only)	1					
Number of keys	2					
Central locking	2					
Remote locking	•					
Sat. Nav. (basic test only)			.,			
Reversing camera			1			
neversing carriera						

I have read and understood this condition guide.

Name: .....

Signature: .....