

Report ID: 55,977 Version: 2 Created: 16 Jul 2018

Make:	Mazda	Model:	CX-9	Body Style:	SUV		Pass	Fail	N/A
Year:	2,011	Registration:	LMA430	Reg Expiry:	28 Jul 2018	Engine		1	
WoF Expiry:	12 Jul 2019	Odometer:	157,175 Kms	Good No:	18254019	Oil level	~		
VIN:	JM0TB10A4B0304964	Next Service:	167000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust	s sc			710	HIVS	Operation	~		
PT = paint defe	ect NP				10111	Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				24114	CV joints	~		
* = decals	- Alt	10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W – significant			SC SC			Performance	~		
Body Insr	ection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
<u>body inspection comments</u>						Tyres (lowest observed tread depth of tyres)			
						Left front 7.5 m			mm
						Right front	7	.4	mm
						Left rear	7	.8	mm
Conditions During Body Inspection: Wet						Right rear	7.7 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Comoto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	iu					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
	ning Machanism					Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Brad Date: 11 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: