

## **Basic Vehicle Condition Guide**

Report ID: 55,960

Version: 2


Created: 28 Jul 2018

Fail N/A

Make: Model: Mitsubishi Pajero **Body Style:** SUV Year: 2,005 Registration: CRL959 Reg Expiry: 01 Jul 2018 WoF Expiry: **Odometer:** 02 Jul 2019 **Good No:** 181,512 Kms 18254504 VIN: JMFLYV77W5J002964 **Next Service: Service History:** 16/1/19 Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

**General Comments** 

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Kms: 100,055

	1 433	i an	14/7	
Engine				
Oil level	~			
Smoke & fumes	\( \times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	V			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	7	.0	mm	
Right front	7.0		mm	
Left rear	4.5		mm	
Right rear	4.5		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	\( \triangle \)			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	V			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	<b>V</b>			
Window winder RL				
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1			
Central locking	~			
Remote locking		~		
Sat. Nav. (basic test only)			~	
Reversing camera			~	

Signature: .....

Inspected by: Jake Date: 04 Jul 2018

Name: .....