

Report ID: 18,254,625 Version: 2 16 Jul 2018 Created:

Make:	Holden	Model:	Commodore	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,007	<b>Registration:</b>	EFL417	Reg Expiry:	18 Aug 2018	Engine	I	I	1
WoF Expiry:	24 Jul 2019	Odometer:	246,277 Kms	Good No:	18254625	Oil level	~		
VIN:	6G1ZK84B86L973612	Next Service:	255000	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	D	<u>~</u> ⊘	LSC			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc			ZIS	S SC W	Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		-
*= decals						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S P S W PT						Performance	~		
Dedution		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed trea		n of tyre	es)
Poor paint repairs roof and left rear quarter									mm
						Right front	5.0		mm
						Left rear	5.0		mm
Conditions During Body Inspection:						Right rear	5.0		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance		~	
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation			
Interior Comments						Electrical / Accessories	•		
Seats Average						Head lights	~		
						Tail lights		~	
Carpets	Average					Indicators	~	-	
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	I	1
Road Conditions During Test Drive: Dry						Central locking	2 V		
Road Conditions During Test Drive: Dry						Remote locking	-	~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)		-	~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
L	-	•	••••••						
Inspected by: Greg Morgan Date: 29 Jun 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....