

Report ID: 18,255,170 Version: 2 11 Jul 2018 Created:

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,005	Registration:	JRU371	Reg Expiry:	02 Apr 2019	Engine	1		1
WoF Expiry:	26 Jun 2019	Odometer:	106,154 Kms	Good No:	18255170	Oil level	~		
VIN:	WVWZZZ1KZ5W1688(Next Service:	114000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		-0	<u>s</u>	$- \square$	PT	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect C = crack P = pin dent						Operation	~		
						Noise	~		
						Clutch			~
						CV joints	~		-
* = decals SC 919 PT						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W D S W S						Performance	~		
Dealerteen	<u></u>	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
Rear bumper alignment left side								mm	
						Right front			mm
						Left rear	6		mm
Conditions During Pody Inspection:						Right rear			
Conditions During Body Inspection: Dry						Spare	6 mr Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension Yes			
		·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Average						Head lights			
						Tail lights	~		
Carpets	Average						~		
Danala	Average					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Rear cup h	olders missing				Window winder FL	~		
						Window winder FE	~		
General C	Comments					Window winder PK	~		
						Window winder RL	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys			
						Central locking	1 V		
Road Conditions During Test Drive: Dry						Remote locking			
Engine Timing Mechanism: Cambelt						-	~		
Evidence of Cam Belt Replacement: Yes Kms: 105,092						Sat. Nav. (basic test only)			v
		I				Reversing camera			~
Inspected by: John Lindsay Date: 11 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: