

Basic Vehicle Condition Guide

Report ID: 18,255,428


Version: 2

Created: 04 Jul 2018

Make: Model: Hyundai 130 **Body Style:** Wagon Year: 2,010 Registration: FSN327 Reg Expiry: 20 Jul 2019 WoF Expiry: **Odometer:** 30 Jan 2019 **Good No:** 18255428 167,111 Kms VIN: KMHDB81DMBU10860 **Next Service:** 165000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Underbody corrosion

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

Dry

General Comments

Rear seats bolted down, unable to confirm if storks are installed/missing

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: John Lindsay Date: 04 Jul 2018

Name:

| | Pass | Fail | N/A |
|------------------------------|--|--------|----------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | V | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | l | ļ |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tvr | es) |
| Left front | | | mm |
| Right front | 6 | | mm |
| Left rear | 6 | | mm |
| Right rear | 6 | | mm |
| Spare | Yes | | |
| Suspension | | 103 | |
| Suspension performance | V | | |
| Steering performance | <i>'</i> | | |
| Shock absorbers | <i>'</i> | | |
| Air Conditioning / Heater | | | |
| Operation | | | |
| Electrical / Accessories | | | |
| Head lights | | | |
| Tail lights | 1 | | |
| Indicators | 1 | | |
| Dashboard warning lights | | | |
| Wipers (front & rear) | | | |
| Window winder FL | \(\times \) \(\t | | |
| Window winder FR | | | |
| | - | | |
| Window winder RL | \(\times \) | | |
| Window winder RR | <i>'</i> | | |
| Rear view mirrors | | | |
| Radio (basic test only) | <i>'</i> | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | / |

Signature: