

Basic Vehicle Condition Guide

Report ID: 18,255,601

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Coolant condition Performance

Radiator / Hoses (visual)

Created: 03 Jul 2018

Pass

1

~

/


Fail

N/A

Make: Model: Mazda6 **Body Style:** Wagon Mazda Year: 2,005 Registration: CPT554 Reg Expiry: 18 Jul 2018 **WoF Expiry: Odometer: Good No:** 24 May 2018 359,537 Kms 18255601 VIN: JM0GY103100103982 **Next Service: Service History:** 364700 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil low

Oil leak

AC not getting cold Wheel bearings noisy

Interior	Comments
IIIICIIOI	Commencia

Seats	stains
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

CV joint leaking grease Harsh gear changes

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

03 Jul 2018 Inspected by: John Lindsay

Name:

	~	
~		
		~
	~	
	~	
	•	
~		
~		
d depth	of tyr	es)
ft front 6		mm
6		mm
6		mm
6		mm
Yes		
•		
~		
~		
~		
		•
	~	
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
1		
~		
~		
		~
		6 6 7es

Reversing camera

Signature: