

Report ID: 18,256,659 Version: 1 Created: 04 Jul 2018

Make:	Honda	Model:	Integra	Body Style:	Sports Car		Pass	Fail	N/A
Year:	1,994	Registration:	XS4421	Reg Expiry:	26 Jul 2018	Engine	1	I	
WoF Expiry:	11 Dec 2018	Odometer:	184,786 Kms	Good No:	18256659	Oil level	~		
VIN:	7A88G0R0798010243	Next Service:	due	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
					DTCCW	Performance	~		
Key:	SDW	-0	PT SC		PT SC W	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	S D SC W			715	HIL SW	Operation	~		
PT = paint defe		F I		$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch	~		
P = pin dent	HIP				74116	CV joints	~		
* = decals	sc 916			The second	ED PT	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC PT SC W W						Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres			es)
					Left front		.0	mm	
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear		.0	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I				I	Window winder FR	~		
General Comments						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	I	1
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
ц							1	1	1
Inspected by: Dion Mair Date: 03 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: