

Basic Vehicle Condition Guide

Report ID: 18,257,453


Version: 3

Created: 19 Jul 2018

Make: Model: 307 **Body Style:** Hatchback Peugeot Year: 2,007 Registration: DYC719 Reg Expiry: 06 Aug 2018 **WoF Expiry: Odometer: Good No:** 15 Jun 2019 18257453 114,547 Kms VIN: **Next Service:** VF33CRFJF84513316 **Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

RH tail lamp lens cracked

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Good		

Genera	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Cleate	u. 1.	7 Jul 20	-10
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	V		
Performance	~		
Noise	~		
Cooling System	•	•	•
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	!	
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	'	ı	
Performance	1		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	- 2	2	mm
Right front	2	2	mm
Left rear	6		mm
Right rear	3		mm
Spare		Yes	
Suspension	ı		
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		!	
Operation	~		
Electrical / Accessories		ı	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	\(\times \) \(\t		
Window winder FL	~		
Window winder FR	~		
Window winder RL			
Window winder RR	\(\triangle \)		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	ı	
Central locking	~		
Remote locking		~	
Sat. Nav. (basic test only)			~
Reversing camera			

I have read and understood this condition guide.

Mathew Varghese

Name:

Signature:

19 Jul 2018

Reversing camera