

## **Basic Vehicle Condition Guide**

Report ID: 18,257,482


Version: 1

Created: 18 Jul 2018

Make: Model: Mazda CX-5 **Body Style:** SUV Year: 2,014 Registration: HQS197 Reg Expiry: 10 Sep 2018 **WoF Expiry: Odometer: Good No:** 11 Sep 2018 18257482 82,172 Kms VIN: **Next Service: Service History:** JM0KE103100266886 83800

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

## **General Comments**

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Dion Mair Date: 04 Jul 2018

	Pass	Fail	N/A
Engine	•	•	•
Oil level	~		
Smoke & fumes	~		
Performance	\( \times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	ı		1
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	⊥ ≥s)
Left front			mm
Right front	3		mm
Left rear	3		mm
Right rear		3	mm
Spare		Yes	
Suspension		103	
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater			1
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	<b>v</b>		
Dashboard warning lights			
Wipers (front & rear)	~		
Window winder FL	\( \triangle \)		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	<i>V</i>		
Remote locking			
Sat. Nav. (basic test only)	V		
Reversing camera	~		
eversing cumeru			

I have read and understood this condition guide.

Name: .....

Signature: .....