

Report ID: 55,688 Version: 1 Created: 24 Jul 2018

Make:	BMW	Model:	318	Body Style:	Sedan	1		Pass	Fail	N/A	
Year:	2,003	Registration:	GAE630	Reg Expiry:	17 May 2019		Engine				
WoF Expiry:	25 Jul 2019	Odometer:	142,900 Kms	Good No:	18258141		Oil level	~			
VIN:	WBAAZ72090NG2352	Next Service:	152000	Service Histor	y: No		Smoke & fumes	~			
						1	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.		Coolant condition	~			
						1	Performance	~			
Key:	SC	-0		-01-			Radiator / Hoses (visual)	~			
S = scratch D = dent							Transmission		1	.I	
B = rust sc s $R = rust$							Operation	~			
PT = paint defect							Noise	~			
C = crack							Clutch			~	
P = pin dent							CV joints	~			
* = decals SC S 9 9							Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs S S S							Performance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Hand Brake	V		<u> </u>	
RR window not working - switch broken							Tyres (lowest observed tread depth of tyres)				
An window hot working - switch broken							Left front		5	mm	
							Right front		5	mm	
							Left rear		.0	mm	
Conditions During Body Inspection: Wet						1	Right rear		2	mm	
conditions builling body inspection. Wet							Spare		Yes		
Under Carriage & Under Bonnet Inspection Comments							Suspension				
Oil leaks							Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater		1		
							Operation	~			
Interior Comments							Electrical / Accessories				
Seats	Average						Head lights	~			
	Average						Tail lights	~			
Carpets	/ Werage						Indicators	~		<u> </u>	
Panels	Average						Dashboard warning lights	~		1	
	Average	Δυστοσο					Wipers (front & rear)	V			
Dashboa	ird						Window winder FL	~		<u> </u>	
	ľ						Window winder FR	V		1	
	<u>Comments</u>						Window winder RL	~		<u> </u>	
Rear Tyre low							Window winder RR		~	1	
							Rear view mirrors	~		1	
							Radio (basic test only)	~		<u> </u>	
							CD (basic test only)	~			
							Number of keys	1	I	1	
Road Conditions During Test Drive: Dry						٦	Central locking	~			
			у]	Remote locking	V		1	
Engine Ti	ming Mechanism:	Timing	Chain				Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:							Reversing camera			~	
						_	_	1	1		
Inspected by: Scott Date: 04 Jul 2018											

I have read and understood this condition guide.

Name:

Signature: