

Basic Vehicle Condition Guide

Report ID: 18,258,419

Pass

Version: 2

Created: 10 Sep 2018


Fail

N/A

Make: Model: Hyundai ТВ **Body Style:** Hatchback Year: 2,005 Registration: Reg Expiry: FMJ453 25 Aug 2018 **WoF Expiry: Odometer: Good No:** 18258419 10 Aug 2019 82,661 Kms VIN: KMHBT51DR6U46528 **Next Service: Service History:** 77,221kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

R/H wing mirror cracked.

Paint defect on door handles, wing mirrors, grille, bumper & I/h A pillar.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|----------------------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | cargo shelf missing. | | |
| Dashboard | Average | | |

General Comments

Good little hatch.

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Daryll Timms

Evidence of Cam Belt Replacement: No

Kms:

| Engine | | | |
|------------------------------|--------------|---------|-----|
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | \(\times \) | | |
| Noise | ~ | | |
| Cooling System | • | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 6 | 5.0 | mm |
| Right front | 6.0 | | mm |
| Left rear | 5.0 | | mm |
| Right rear | 5.0 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | _ | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | v | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 3 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | 1 |

I have read and understood this condition guide.

Name:

Signature:

09 Jul 2018

1

Reversing camera