

Basic Vehicle Condition Guide

Report ID: 18,258,538


Version:

Created: 05 Jul 2018

Make: Model: Holden Colorado **Body Style:** Utility Year: Registration: Reg Expiry: 2,013 HCJ581 01 Apr 2019 WoF Expiry: **Odometer:** 04 Oct 2018 **Good No:** 158,902 Kms 18258538 VIN: MMU148EH0DH67553 **Next Service: Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips on front windscreen Radio antenna missing LH tail light damaged Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Underbody surface rust

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

RH under dash panel insecure Steering wheel leather damaged Aftermarket screen fitted on top of the dash

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Xinghui Lin Date: 05 Jul 2018

Name:

Engine Oil level Smoke & fumes Performance Noise	V V		
Smoke & fumes Performance	v v		
Performance	~		
Noise	/		
i l	~		
Cooling System		•	
Coolant condition	~		
Performance	v v		
Radiator / Hoses (visual)	~		
Transmission			1
Operation	~		
Noise	~		
Clutch	VV		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		Ι
Hand Brake	~		
Tyres (lowest observed tread	depth	of tvre	L es)
Left front		 4	mm
Right front			mm
Left rear		-	mm
Right rear	4		mm
Spare	4 Yes		
Suspension		163	
Suspension performance	_		
Steering performance	<u> </u>		
Shock absorbers	<u> </u>		
Air Conditioning / Heater			
Operation			
Electrical / Accessories			
Head lights			
Tail lights	~		
Indicators			
Dashboard warning lights	•		
Wipers (front & rear)	V V V		
Window winder FL			
Window winder FR	<u> </u>		
Window winder RL			
Window winder RR	ン ン ン		
Rear view mirrors			
Radio (basic test only)	V		
CD (basic test only)	<u> </u>		
Number of keys	2		
	~		
Central locking			
Remote locking	~		
	'		~

Signature: