

Report ID: 18,258,658 Version: 1 Created: 04 Jul 2018

Make:	Mazda	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2,007	Registration:		Reg Expiry:		Engine	1		1	
WoF Expiry:	,	Odometer:	95,965 Kms	Good No:	18258658	Oil level	~			
VIN:	7AT0C12HX18102816	Next Service:	105,970kms	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~			
						Performance	~			
Key:		-0				Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust				215	HIV	Operation	~			
PT = paint defe				$\left(\left \left(\right) \right\rangle \right)$		Noise	~			
C = crack						Clutch	~			
P = pin dent	HID				7414	CV joints	~			
* = decals	MAR			-Jul		Wheel bearings	~			
SC = stone chips						Brakes				
W = significant						Performance	~			
Body Incr	oction Commonts	Note: som	e defects & blemishes	may not be disp	played in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)				
						Left front		1	mm	
						Right front		1	mm	
						Left rear	4	1	mm	
Conditions During Body Inspection: Dry					Right rear	4 mm		mm		
					Spare	Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Tidy .						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater			1	
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
	1					Window winder FR	~			
General Comments					Window winder RL	~				
Nice little h	atch .					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry Central locking							~			
		. 51170.				Remote locking	~			
Engine Tir	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
Inspected	Inspected by: Daryll Timms Date: 04 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: