

I have read and understood this condition guide.

Report ID: 18,259,303 Version: 1 26 Jul 2018 Created:

Signature:

Make:	Suzuki	Model:	Grand Vitara	Body Style:	SUV][Pass	Fail	N/A	
Year:	2,013	Registration:	HCC613	Reg Expiry:	29 Sep 2018	Engine			1	
WoF Expiry:	23 Sep 2018	Odometer:	54,673 Kms	Good No:	18259303	Oil level	~			
VIN:	JSAJTDA4V00275204	Next Service:	due	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechar	ical inspection prior to	purchase and t	nis can be arranged fo	or an additional o	charge.	Coolant condition	~			
						Performance	~			
Key:	SW	-0		-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust S SC W						Operation	~			
PT = paint def				$\left(\right)$		Noise	~			
C = crack						Clutch			~	
P = pin dent					7414	CV joints	~		•	
* = decals	sscw 91			- No	ETP-	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S D SC W S W S W						Performance	~			
D. L.L.		Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)	
					Left front 2.0 mm					
						Right front			 mm	
						Left rear		.0	mm	
Candition		a a ati a m.	2			Right rear		.0	 mm	
Conditions During Body Inspection: Dry						Right rear 2.0 mm Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	-	•				Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats Good						Head lights				
Jeals						Tail lights	~ ~			
Carpets	Good					Indicators	~ ~			
Dawala	Good					Dashboard warning light				
Panels						Wipers (front & rear)	\$ V V			
Dashboa	rd Good					Window winder FL	~ ~			
	I					Window winder FE	~			
General Comments						Window winder RL	~ ~			
						Window winder RR	~ ~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys				
Dead Conditions Duving Test Driver						Central locking	2	2		
Road Conditions During Test Drive: Dry						Remote locking	~ ~ ~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)				
Evidence of Cam Belt Replacement: Not Applicable Kms:									~	
						Reversing camera	~			
Inspected by: Dion Mair Date: 09 Jul 2018										

Name: