

Report ID: 18,259,433 Version: 3 16 Aug 2018 Created:

Make:	Ford	Model:	Territory	Body Style:	SUV		Pass	Fail	N/A
Year:	2,011	<b>Registration:</b>	GBW211	Reg Expiry:	27 Sep 2018	Engine	I		
WoF Expiry:		Odometer:	125,411 Kms	Good No:	18259433	Oil level	~		
VIN:	6FPAAAJGATBY38060	Next Service:	130,000kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC W		S P SC SC W		SC	Performance	~		
Key:	ISC ILV	-0	S P SC SC W	$\neg \bigcirc \square$		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust	s sc			210	HIVS	Operation	~		
PT = paint defe					17111	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HP				74116	CV joints	~		
* = decals	sc Alt			10	ED S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W – significan	SC W		S SC SC W		SC W	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Stone chips on screen.						Tyres (lowest observed tread	d depth	of tyre	s)
						Left front	5.0 mm		
						Right front	4.	0	mm
						Left rear	2.	0	mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
OK.						Suspension performance	~		
						Steering performance	~		
	Shock absorbers	~							
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	3 head res	ts missing.				Head lights	~		
Comoto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashh	Average					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
	-					Window winder FR	~		
General Comments						Window winder RL	~		
Good 7 seat	ter SUV.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
L						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking									
Remote locking							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Daryll Timms Date: 09 Jul 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....