

Basic Vehicle Condition Guide

Report ID: 18,259,595


Version:

Created: 17 Jul 2018

Make: Model: Holden Captiva 7 **Body Style:** SUV Year: 2,012 Registration: Reg Expiry: **GKF640** 01 Jul 2019 **Odometer:** WoF Expiry: 10 Jul 2019 **Good No:** 18259595 162,330 Kms VIN: **Next Service: Service History:** KL3CA264JBB150652

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips and small crack in the windscreen,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	stereo needs a code to work ,		

General Comments

Stereo needs a code to work,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Kms: Not Applicable

17 Jul 2018 Inspected by: Donovan Matara Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	1		ı
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	 es)
Left front			mm
Right front			mm
Left rear	3		mm
Right rear	5		mm
Spare	Yes		
Suspension		163	
Suspension performance	~		
Steering performance	· ·		
Shock absorbers	V		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	~		
Tail lights			
Indicators	V		
Dashboard warning lights	1/		
Wipers (front & rear)	\(\times \)		
Window winder FL	~		
Window winder FR	-		
Window winder RL	~		
	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	<i>'</i>		
CD (basic test only)	~		
Number of keys	2	ı	1
Company Haraldan a			1
Central locking	~		
Remote locking	.		
	.		~

Signature: