

Report ID: 18,259,684 Version: 1 11 Jul 2018 Created:

Make:	Subaru	Model:	Trezia	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,011	Registration:	KUN214	Reg Expiry:	03 Sep 2018	Engine			
WoF Expiry:	27 Jul 2018	Odometer:	56,369 Kms	Good No:	18259684	Oil level	~		
VIN:	7AT0GF24X17001145	Next Service:	due	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	V		
Key:	sc	-0				Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust	- HE			715	S D SC W	Operation	~		
PT = paint defe		F		$\left(\left \right\rangle \right)$		Noise	V		
C = crack						Clutch			~
P = pin dent	HID				거네	CV joints	~		
* = decals	- Alk			- Jul	AID	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance			
Dealer		Note: som	ne defects & blemishes	may not be disc	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	•	of tvre	s)
					Left front 3.0 mm				
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Rody Inspection:						Right rear			 mm
Conditions During Body Inspection: Dry						Spare	5.0		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
		•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation	~		
Interior Comments						Electrical / Accessories			
Good						Head lights			
Seats							-		
Carpets	Good					Tail lights Indicators	v		
D	Good					Dashboard warning lights	レ レ		
Panels						Wipers (front & rear)	-		
Dashboa	rd Good					Window winder FL	~		
						Window winder FL Window winder FR	v		
General (<u>Comments</u>					Window winder FR Window winder RL	v		
						Window winder RL Window winder RR	V 		
						Rear view mirrors	V 		
						Rear view mirrors Radio (basic test only)	v		
						CD (basic test only)	v		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine Ti	ming Mechanism:	Timina (Chain			Remote locking	~		
						Sat. Nav. (basic test only)			~
			lot Applicable	11113.		Reversing camera	~		
Inspected by: Dion Mair Date: 10 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: