

Report ID: 18,260,486 Version: 1 10 Jul 2018 Created:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A	
Year:	2,017	Registration:	KRY785	Reg Expiry:	30 Jul 2018	Engine	1	L		
WoF Expiry:		Odometer:	59,861 Kms	Good No:	18260486	Oil level	~			
VIN:	MPATFR85JHT003189	Next Service:	due	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	lical inspection prior to	purchase and th	his can be arranged to	r an additional o	narge.	Coolant condition	~			
	W					Performance	~			
Key:		-0		500-		Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission	mission			
R = rust	w AR			210		Operation	~			
PT = paint defe	ect NP				1111	Noise	~			
C = crack						Clutch	~			
P = pin dent	sc de				24116	CV joints	~			
						Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
W = significan	SW					Performance	~			
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~			
Front tyres edge worn						Tyres (lowest observed tread depth of tyres)				
						Left front	2	.0	mm	
						Right front	2	.0	mm	
						Left rear	2	.0	mm	
Conditions During Body Inspection: Dry						Right rear	2.0 1		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Front brake	pads low					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	Conditioning / Heater			
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpote	Average					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dachhar	Good					Wipers (front & rear)	~			
Dashboa	iiu					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected by: Dion Mair Date: 09 Jul 2018										

I have read and understood this condition guide.

Name:

Signature: