

Report ID: 18,260,687 Version: 1 20 Jul 2018 Created:

Make:	Hyundai	Model:	lx35	Body Style:	SUV		Pass	Fail	N/A
Year:	2,012	Registration:	GFP453	Reg Expiry:	30 Jan 2019	Engine	1		
WoF Expiry:	02 Jul 2019	Odometer:	123,656 Kms	Good No:	18260687	Oil level	~		
VIN:	KMHJT81BMCU45097	Next Service:		Service Histor		Smoke & fumes	~		
			·			Performance	~		
	port is not a warranty	unting is goods	for one and miles as	Dauta hava nat	heen dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
		_				Performance	~		
Key:		-0	SW W			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sscw			1n-	BID SW	Operation	~		
R = rust PT = paint defe				\int	JHIH	Noise	~		
C = crack					SC W	Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	RPSC PIC			AL.	ELIP SD	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance		~	
		Note: som	he defects & blemishes	may not be disn	laved in the diagram	Hand Brake	~	V	
Body Insp	pection Comments	10000.3011	le delects & blemisnes	inay not be disp	layed in the diagram		-	- f t	
					Tyres (lowest observed tread depth of tyres)				
						Left front		.6	mm
						Right front		.4	mm
						Left rear	6		mm
Conditions During Body Inspection: Dry						Right rear	6.6 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Underbody surface rust. Front & rear brake disc/rotors worn and will need to be replaced soon						Suspension			
Underbody	Surface rust. Front & rea	ar brake disc/rolo	ors worn and will need	to be replaced s	oon	Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
	Card					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		
Canada						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	-		-			Remote locking	~		
-	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Jason Young Date: 20 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: