

Report ID: 18,261,559 Version: 2 27 Jul 2018 Created:

Make:	Mazda	Model:	CX-5	Body Style:	SUV		Pass	Fail	N/A	
Year:	2,014	Registration:	HQ\$200	Reg Expiry:	10 Sep 2018	Engine				
WoF Expiry:	02 Aug 2019	Odometer:	117,998 Kms	Good No:	18261559	Oil level	~			
VIN:	JM0KE103100265833	Next Service:	123000	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:		-0	S SC	-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission			1	
D = dent R = rust	S P SC			ZIS	HILLS	Operation	~			
PT = paint defe				$\left[ \left( \right) \right]$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HE				74116	CV joints	~			
* = decals	ssc 916			The second		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
vv = significant	SC		S		S D SC	Performance	~			
Body Insr	ection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)				
								mm		
						Right front		3	mm	
						Left rear	1	.5	mm	
Conditions During Body Inspection: Dry						Right rear		2 mm		
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	ra					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
	-					Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~			
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected by: Donovan Matara Date: 27 Jul 2018										

I have read and understood this condition guide.

Name: .....

Signature: .....