

Report ID: 18,262,580 Version: 1 Created: 17 Jul 2018

Make:	Ford	Model:	Mondeo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,012	Registration:	GNS114	Reg Expiry:	11 Jan 2019	Engine			
WoF Expiry:	12 Oct 2018	Odometer:	126,685 Kms	Good No:	18262580	Oil level	~		1
VIN:	WF0EXXGBBECD3829			Service Histor		Smoke & fumes		~	<del> </del>
	WFUEXXGBBECD3829:	Next Service.	140,000kms	Service mistor	y: Yes			V	+
Note: This report is not a warranty					Performance	~		<u> </u>	
	a guide only. Conside					Noise		~	
	sting undertaken. The vical inspection prior to					Cooling System			<del></del>
					-	Coolant condition	~		<u> </u>
Key:		$\sim$				Performance	~		
S = scratch		$\sim$		2(O)		Radiator / Hoses (visual)	~		
D = dent				100	A T	Transmission	_		
R = rust	sc PIA			10		Operation	~		
PT = paint def	ect NP	1				Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				7414	CV joints	~		
* = decals	PSC 91					Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D S						Performance	~		
		Note: son	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		+
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							est observed tread depth of tyres)		
						Left front			_
							6		mm
						Right front	6		mm
						Left rear	7		mm
Conditions During Body Inspection: Dry						Right rear	5	.5	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Under Ca	rriage & Under Bor	inet inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
		Operation	~						
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		1
	Good					Tail lights	~		
Carpets	Guu					Indicators	~		+
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		+
						Window winder FL	-		
General (	Comments						~		
Visual smoke						Window winder RL	~		
Engine noisy						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspected by: Ca Thach						Date: 17 Jul 201	8		
I have read	and understood th	is condition c	uide. Name:			Signature:			