

Report ID: 18,263,334 Version: 1 19 Jul 2018 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2,015	Registration:	JEE659	Reg Expiry:	17 Sep 2018	Engine			
WoF Expiry:	•	Odometer:	119,439 Kms	Good No:	18263334	Oil level	~		
VIN:	MMU148LK0GH60204		134,000kms	Service Histor		Smoke & fumes	~		
			134,000km3		. 110	Performance	~		
	port is not a warranty		~ · · ·	-		Noise	~		-
	a guide only. Conside sting undertaken. The					Cooling System	•		
a full mechan	ical inspection prior to	purchase and the	nis can be arranged f	or an additional o	harge.	Coolant condition	~		1
		_				Performance	~		
Key:	sc	-0	SPW W			Radiator / Hoses (visual)	~		+
S = scratch	STE	A CO			X	Transmission	•		
D = dent	sc 6/6			100	HID W	Operation	~		T
R = rust				TIO	JHIN	Noise	~		
PT = paint defects C = crack	ect			+	SC	Clutch			
P = pin dent	Ho				JUII ——	CV joints			~ ~
* = decals	PSC PSC				ENR -	,			
SC = stone chi	ps US	VA		10		Wheel bearings Brakes	~		
W = significant scuffs S S P S S P									T
		Notorer			laved in the diagram	Performance	<b>v</b>		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		-f+	<u> </u>
						Tyres (lowest observed tread		-	
						Left front	7.	.1	mm
						Right front	7.	.3	mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Dry						Right rear	6.3 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
<u>Under Ca</u>	inage & onder bor	met inspectic	ncomments			Suspension	1		
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
_	_					Window winder FR	~		
<u>General (</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		1
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		•
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
						Remote locking	~		1
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		1
						L			1
Inspecte	d by: Jason Young					Date: 19 Jul 201	8		
I have read	and understood th	is condition q	uide. Name:			Signature:			