

Basic Vehicle Condition Guide

Report ID: 18,264,216


Version: 2

Created: 05 Oct 2018

Make: Model: **BMW** X5 **Body Style:** SUV Year: 2017 Registration: KNE515 Reg Expiry: 27 Apr 2019 **WoF Expiry: Odometer: Good No:** 28 Apr 2020 25,874 Kms 18264216 VIN: **Next Service:** WBAKS420900J69552 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Tailgate noisy

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Clean

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Stuart Melbourne

	Pass	Fail	N/A		
Engino	Pass	Ган	IN/A		
Engine Oil level ✓					
Smoke & fumes					
	\(\times \)				
Performance	•				
Noise	•				
Cooling System			1		
Coolant condition	<i>V</i>				
Performance	V				
Radiator / Hoses (Visual)					
Transmission		1			
Operation	~				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread	depth	of tyre	es)		
Left front	4	.0	mm		
Right front	4.0		mm		
Left rear	5.0		mm		
Right rear	5.0		mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	~				
Shock absorbers	~				
Air Conditioning / Heater					
Operation	~				
Electrical / Accessories					
Head lights	~				
Tail lights	~				
Indicators	~				
Dashboard warning lights	~				
Wipers (front & rear)	~				
Window winder FL	~				
Window winder FR	~				
Window winder RL	~				
Window winder RR	~				
Rear view mirrors	~				
Radio (basic test only)	~				
CD (basic test only)	~				
Number of keys	2		I		
Central locking	∠ ✓				
Remote locking	~				
Sat. Nav. (basic test only)	v				
Reversing camera	V				
eversing cumera			I		
Date: 06 Jul 2018					

I have read and understood this condition guide.

Name:

Signature: