

Report ID: 18,264,631 Version: 2 Created: 08 Jul 2018

Make:	Honda	Model:	Odyssey	Body Style:	Wagon		Pass	Fail	N/A
Year:	1,999	<b>Registration:</b>	EPR483	Reg Expiry:	13 Jul 2018	Engine	1	I	1
WoF Expiry:	30 Jul 2018	Odometer:	166,898 Kms	Good No:	18264631	Oil level	~		
VIN:	7A88G610708130524	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition		~	<u> </u>
						Performance	~		
Key:	s s	-0	IS IS	-161-	S D	Radiator / Hoses (visual)	~		
S = scratch						Transmission			<u> </u>
D = dent						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	-		~
P = pin dent						CV joints	~		-
*=decals SD 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SD W S S S W SD						Performance			
						Hand Brake			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Hand Brake <b>Tyres</b> (lowest observed tread depth of tyres)		
FR power window not working , noise from the door Rear bumper misaligned							1		
Rear badge missing, Water inside both tail lamps, Wiper blades rusty						Left front		5	mm
Rust on tail door hinge area and right roof gutter RL door hinges noisy. Glove box door insecure						Right front		5	mm
						Left rear		3	mm
Conditions During Body Inspection: Wet						Right rear		3	mm
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
						Suspension	1.		1
Coolant diluted Battery ins						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation		~	
Interior Comments Average						Electrical / Accessories	-		<del></del>
Seats	Average					Head lights	~		
Carpets	Poor					Tail lights	~		
						Indicators	~		
Panels	Poor					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
Dashboa	ru –					Window winder FL	~		
	-					Window winder FR		~	
General Comments						Window winder RL	~		
Front suspension weak FL window winding slow						Window winder RR	~		
Power window master switch panel, grab handle insecure						Rear view mirrors	~		
AC not working						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	2		•
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
			1	I					
Inspected by: Mathew Varghese Date: 08 Jul 2018									
I have read	and understood th	is condition c	guide. Name: .			Signature:			