

Report ID: 18,264,762 Version: 3 Created: 03 Oct 2018

Make:	Ford	Model:	Mondeo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2012	Registration:	LMF121	Reg Expiry:	15 Jan 2019	Engine	I	1	
WoF Expiry:	20 Jul 2019	Odometer:	140,396 Kms	Good No:	18264762	Oil level	~		
VIN:	WF0EXXGBBECR60575	Next Service:	142000	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0	S S			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation	~		
						Noise	~		
PT = paint defect C = crack						Clutch			~
P = pin dent						CV joints	~		V
* = decals SC PP						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W									
		Note com			laved in the diagram		~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake			
Damage right sill						Tyres (lowest observed tread depth of tyres)			
Front bumper grill trim loose						Left front	6		mm
						Right front	6	.0	mm
[Left rear	6	.0	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
<u>Under Ca</u>	mage & Under Bor	inet inspectic	on comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	stains					Head lights	~		
Correcto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	<i>·</i>		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
Inspected by: John Lindsay Date: 21 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: