

Report ID: 18,264,829 Version: 1 25 Jul 2018 Created:

Make:	Nissan	Model:	Note	Body Style: Hatchback		Pass	Fail	N/A	
Year:	2,009	Registration:	Hote	Reg Expiry:	Engine		-		
WoF Expiry:		Odometer:	58,796 Kms	Good No: 18264829	Oil level	~			
VIN:	7AT0DH79X18355495	Next Service:	69,000kms	Service History: No	Smoke & fumes	~			
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		03,0001113		Performance	~			
	port is not a warranty		· · · ·		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling System				
					Coolant condition				
					Performance	~			
Key:		-0			Radiator / Hoses (visual)	~			
S = scratch	Se	10			Transmission	V			
D = dent	- Alle				Operation	~			
R = rust					Noise	~			
PT = paint def C = crack	ect III				Clutch	V		~	
P = pin dent	Htc	KI			CV joints	~			
* = decals	- MIK				Wheel bearings	~			
SC = stone chips					Brakes				
W = significant scuffs								<u> </u>	
		Notor con	L defects ^e blomisbor	may not be displayed in the diagram	Performance Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							<i>C</i> .	Ļ	
					Tyres (lowest observed tread depth of tyres)				
					Left front	7		mm	
					Right front	7		mm	
					Left rear	7		mm	
Conditions During Body Inspection: Dry					Right rear	7	7 mm		
					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Tidy .					Suspension performance	~		<u> </u>	
					Steering performance	~		<u> </u>	
					Shock absorbers	~			
					Air Conditioning / Heater				
Interior Comments					Operation 🖌				
Interior Comments					Electrical / Accessories				
Seats	Good				Head lights	~			
Carpote	Good				Tail lights	~			
Carpets					Indicators	~			
Panels	Good				Dashboard warning lights	~			
	Good				Wipers (front & rear)	~			
Dashboa	ira				Window winder FL	~			
	_				Window winder FR	~			
General Comments					Window winder RL	~			
Nice Note.					Window winder RR	~			
					Rear view mirrors	~			
					Radio (basic test only)	~			
					CD (basic test only)	~			
					Number of keys	1			
Road Conditions During Test Drive: Dry					Central locking	~			
	-		- • J		Remote locking			~	
Engine Timing Mechanism: Timing Chain					Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:	Reversing camera			~	
Inspector	Inspected by: Daryll Timms Date: 25 Jul 2018								
Inspecte						5			

I have read and understood this condition guide.

Name:

Signature: