

## **Basic Vehicle Condition Guide**

Report ID: 18,265,467


Version:

Created: 13 Aug 2018

Make: Model: **Body Style:** Utility Nissan Navara Year: 2,007 Registration: Reg Expiry: EGA745 06 Dec 2018 WoF Expiry: **Odometer: Good No:** 08 Jun 2019 202,581 Kms 18265467 VIN: **Next Service: Service History:** VSKCVAD40A0252779 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Tailgate not shutting properly, suspect bent hinges. Paint damage on deck hardlid. Damage on step in rear bumper, not secure. Stonechips on windscreen. RF spotlight blanking plate missing. Wear on RF seat, steering wheel and both feont door cards. Odour in cab. Wear on RF door body rubber.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Average condition.

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

## **General Comments**

Crack in cover over speedo.

Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain** 

**Evidence of Cam Belt Replacement:** Kms: Not Applicable

Inspected by: Roger King Date: 13 Aug 2018

Name: .....

	Pass	Fail	N/A
Engine			ı
Oil level	•		
Smoke & fumes	\( \times \)		
Performance	~		
Noise	•		
Cooling System		1	1
Coolant condition	~		
Performance	<b>V</b>		
Radiator / Hoses (visual)	~		
Transmission		1	
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	1	.1	mm
Right front	2		mm
Left rear	11		mm
Right rear	11		mm
Spare		Yes	
Suspension	•		
Suspension performance	~		
Steering performance	<i>V</i>		
Shock absorbers	~		
Air Conditioning / Heater		!	•
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights			
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	V V V V V		
Window winder RL	~		
Window winder RR	l		
Rear view mirrors	~		
Radio (basic test only)	\( \triangle \)		
CD (basic test only)	~		
Number of keys	1		1
Central locking	·		
Remote locking	~		
Sat. Nav. (basic test only)			<b>1</b>
Reversing camera			<i>y</i>
eversing cullicia			

Signature: .....