

Report ID: 18,266,225 Version: 2 26 Jul 2018 Created:

Make:	Toyota	Model:	Landcruiser	Body Style:	SUV		Pass	Fail	N/A
Year:	1,999	Registration:	KZP643	Reg Expiry:	31 Aug 2018	Engine	1	I	1
WoF Expiry:	24 Nov 2018	Odometer:	390,406 Kms	Good No:	18266225	Oil level	~		
VIN:	JT111TJA008008619	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	a Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	iical inspection prior to	purchase and t	his can be arranged f	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	S SC	501-		Radiator / Hoses (visual)	~		-
S = scratch						Transmission			
D = dent R = rust		1		215	HIL	Operation	~		
PT = paint def		FI		$\left[\left(\right) \right]$		Noise	~		
C = crack				$+ \mathbb{N}$		Clutch			~
P = pin dent	HIS				74114	CV joints	~		-
* = decals	PSC 91			700		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significan	s SC		S SC S SC	796		Performance	~		
Podylog	action Commont	Note: son	ne defects & blemishe	es may not be disp	played in the diagram	Hand Brake	~		
Body inspection Comments						Tyres (lowest observed trea	d depth	of tyre	1 2s)
Stone chips in the windscreen ,						Left front 8 n			
						Right front		3	mm
						Left rear		3	mm
Conditio	os During Body Ins	nection	W/ot			Right rear		3	mm
Conditions During Body Inspection: Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1.		I
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	drivers se	at ripped ,				Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		1
Panels	Average					Dashboard warning lights	~		
	A					Wipers (front & rear)	~		1
Dashboa	ard Average					Window winder FL	~		1
	I					Window winder FR	~		1
General Comments						Window winder RL	~		1
						Window winder RR	~		1
						Rear view mirrors	~		1
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	2	I	1
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		1
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	cement: N	lo	Kms:		Reversing camera			~
ц							1	1	
Inspecte	d by: Donovan Mata	ra				Date: 26 Jul 201	8		

I have read and understood this condition guide.

Name:

Signature: