

Report ID: 18,266,738 Version: 1 17 Jul 2018 Created:

| Make: | Ford | Model: | Mondeo | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|--------------------------|----------------------|------------------------|---------------------|-----------------------|--|------|------|-----|
| Year: | 2,014 | Registration: | HKS766 | Reg Expiry: | 29 Oct 2018 | Engine | | | |
| WoF Expiry: | 11 Jun 2019 | Odometer: | 66,717 Kms | Good No: | 18266738 | Oil level | ~ | | |
| VIN: | WF0EXXGBBEDD8687 | Next Service: | 80000 | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | eration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | | | | |
| a full mechan | ical inspection prior to | purchase and th | his can be arranged fo | or an additional of | charge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | -(0)- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| D = dent R = rust | | | | 710 | HIV | Operation | ~ | | |
| PT = paint def | ect NP | | | | 17111 | Noise | ~ | | |
| C = crack | | | | | | Clutch | ~ | | |
| P = pin dent | HIP | | | $\langle \rangle$ | 74114 | CV joints | ~ | | |
| * = decals | sc 916 | | | 10 | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| | | | | | | Performance | ~ | | |
| Body Incr | pection Comments | Note: son | ne defects & blemishes | s may not be disp | blayed in the diagram | Hand Brake | ~ | | |
| Right front mudflap missing | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 5 | .0 | mm |
| | | | | | | Right front | 5 | .0 | mm |
| | | | | | | Left rear | 6 | .0 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 6 | .0 | mm |
| | | | | | | Spare Yes | | | |
| Under Ca | rriage & Under Bor | net Inspectio | on Comments | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | _ | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| Carpets | Average | | | | | Tail lights | ~ | | |
| | | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| Dashboa | Average | | | | | Wipers (front & rear) | ~ | | |
| | | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| <u> </u> | | | | | | Number of keys | 2 | | |
| Road Con | ditions During Test | t Drive: | Dry | | | Central locking | ~ | | |
| Enging Ti | ming Machanism | T '' | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | or Cam Beit Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Inspected by: Greg Morgan Date: 16 Jul 2018 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: