

Report ID: 18,267,187 Version: 1 24 Jul 2018 Created:

Make:	Mitsubishi	Model:	Lancer	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,014	<b>Registration:</b>	HMH787	<b>Reg Expiry:</b>	15 Oct 2018	Engine			
WoF Expiry:	24 Jun 2019	Odometer:	56,242 Kms	Good No:	18267187	Oil level	~		
VIN:	JMFLTCX4AEU001986	Next Service:	71,000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	aration is made	for any and mileage	Parts have not	been dismantled or	Noise	~		
diagnostic te	sting undertaken. The	vehicle has beer	driven up to 50km/h	from cold. The	Vendor recommends	Cooling System	1		1
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	LIS	-01-	SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			ZIN		Operation	~		
R = rust PT = paint def				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent					세비	CV joints	~		•
* = decals	sc 916			- No	EITH	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S SC D						Performance	~		
		Note: som	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments			,	ing) ea in the anagram	Tyres (lowest observed tread	-	oftvre	() ()
					Left front 4.9 mm				
						Right front			mm
						Left rear		.2	mm
Canalitian	Dunin - Dadu Inan					Right rear		.9	mm
Conditions During Body Inspection: Wet									
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers			
							~		
						Air Conditioning / Heater			
Interior Comments						Operation			
Good						Electrical / Accessories Head lights			
Seats							~		
Carpets	Good					Tail lights	<b>v</b>		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General (	Comments					Window winder FR	~		
	<u>comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Ti	ming Mechanism	Timine				Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
		ement. N	lot Applicable	11115.		Reversing camera			~
Inspected by: Ian Dunn Date: 24 Jul 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....