

## **Basic Vehicle Condition Guide**

Report ID: 18,268,509

**Pass** 

1

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

**Transmission** 

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 17 Aug 2018

Fail

N/A

1

mm

mm

mm

mm

4.0

4.0

4.0

1

/

/

1

1


1

Yes

Make: Model: **Body Style:** Convertible Volkswagen Beetle Year: Registration: JBR576 **Reg Expiry:** 2,006 16 Apr 2019 WoF Expiry: **Odometer: Good No:** 18268509 27 Jun 2019 130,761 Kms VIN: **Next Service: Service History:** WVWZZZ1YZ6M30139 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Note: some defects & blemishes may not be displayed in the diagram

**Conditions During Body Inspection:** Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

## **General Comments**

Small tear in roof

Road Conditions During Test Drive: Dry

- ,	Remote locking	~		
Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)		~	
Evidence of Cam Belt Replacement: No	Kms:	Reversing camera	~	
Inspected by: Dion Mair	Date: 10 Jul 201	8		
I have read and understood this condition guide.	Name:	Signature:		 