

Report ID: 18,271,416 Version: 1 23 Jul 2018 Created:

Make:	Nissan	Model:	Tiida	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,008	Registration:		Reg Expiry:		Engine	1	I	L
WoF Expiry:		Odometer:	97,023 Kms	Good No:	18271416	Oil level	~		
VIN:	7AT0DH78X18218016	Next Service:	107,018kms	Service Histor		Smoke & fumes	~		
						Performance	~		<u> </u>
	port is not a warranty		6	Danta harra nat	harry discovered and an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
						Coolant condition			
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	GIE			the		Operation	~		
R = rust				1 M	JHIH	Noise	~		
PT = paint defe C = crack				+		Clutch			~
P = pin dent	Ho					CV joints	~		
* = decals	- MIK			AL-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance			T
		Noto: con	ne defects & blemishes		laved in the diagram	Hand Brake	~		
Body Insp	pection Comments	1016.301	le delects & blemisnes	inay not be disp	hayed in the diagram			~ f t	
						Tyres (lowest observed tread depth of tyres)			
						Left front	6		mm
						Right front	6	-	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
Under Carriage & Under Bonnet Inspection Comments					Spare	Yes			
						Suspension			
Tidy .						Suspension performance	~		
						Steering performance	~		
Shock							~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			T
Seats	Good					Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		
	Cood					Indicators	~		
Panels	Good					Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		
						Window winder FR	~		
General Comments Tidy Tiida hatch .					Window winder RL	~			
	atc11.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic tes									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Daryll Timms Date: 23 Jul 2018									
Inspected by. Daty I finitins Date: 23 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: